



STATE OF TENNESSEE
Tennessee Department of Corrections-Northwest Correctional Complex

Invitation to Bid # 32901-11493
AMENDMENT # 1
FOR GUILD DOORS, NORTHWEST CORRECTIONAL
COMPLEX

DATE: 6/16/2020

ITB # 32901-11493 IS AMENDED AS FOLLOWS:

1. This ITB Schedule of Events updates and confirms scheduled ITB dates. Any event, time, or date containing revised or new text is highlighted.

EVENT	TIME (central time zone)	DATE
1. ITB Issued		April 27, 2020
2. Pre-response Conference	1:00 p.m. CST	May 20, 2020
3. Written "Questions & Comments" Deadline	4:30 p.m. CST	June 10, 2020
4. State Response to Written "Questions & Comments"		June 16, 2020
5. Response Deadline	2:00 p.m. CST	July 6, 2020

2. State responses to questions and comments in the table below amend and clarify this ITB.

Any restatement of ITB text in the Question/Comment column shall NOT be construed as a change in the actual wording of the ITB document.

PAGE #	QUESTION / COMMENT	STATE RESPONSE
	1. Please confirm that this is a furnish only job?	Yes
24-53	2. Can you specify which glazing type should be provided? There are multiple "types" provided, but nothing specified	Security grade #2 glazing, no less than 9/16 inches thick. No tinting of the glazing
24-48	3. What hardware set are we to provide? There are multiple hardware sets provided in the 'Door Hardware Specs', but they do not match the 'Hardware Set A' shown in the drawing provided in the 'Guild Door Specs'. Please state whether we	Hardware set A is the hardware to be used

PAGE #	QUESTION / COMMENT	STATE RESPONSE
	should use 'Hardware Set A' or one of the sets in the Door Hardware Specs	
24-48	4. Drawing A1- Group A Hardware does not include the key switch and has an escutcheon which is not needed	Yes a officer key switch is needed. The trim escutcheon is needed for the lock cylinder
1	5. Page 1 of 58 calls for 2 mogul keys per cylinder = 64 keys, is this accurate	64 keys is accurate
2	6. Page 2/58 – Claborn was approved on previous bid, are we approved ?	Yes Claborn is approved
11, section 2.10	7. Page 11/58 2.10, A the indication light does not have a guard, it will be broken. There needs to be a guard over the light	Yes a cover is approved and needed as long as it does not obstruct the visibility of the indicator bulb
24, section 1.7 C	8. Page 24 of 59, 1.7 Maintenance letter C – Spare parts are figured for three sites, spares need to be reduced	Spare parts only need to be provided for 1 site: NWCX
	9. Pages 24-48 are not applicable	These pages are applicable
	10. Pages 49-53 are not applicable, Glass is identified in the front end. 12. Detention Door Glazing. Provide Security Grade #2 glazing no less than 9/16" thick. a. Opening to be no less than 100 square inches with a width not to exceed 5 inches. b. No tinting of glazing is required. c. Installed with stops from the exterior of the door leaving an interior finish without accessible materials and fasteners. d. Installed vertically on the strike side of the door.	Glass is as follows Security grade #2 glazing, no less than 9/16 inches thick. No tinting of the glazing 49-53 is applicable as this addresses warranty issues
	11. The architectural drawing has the hardware set "Group A" listed. This is the hardware set used for the door(s) in question. What is missing from this hardware set is a Threshold and Weather-stripping	Threshold. Provide equal to Reece BAP14(4 inch depth) or approved equal. Weather Stripping. Equal to Reece DB593AF door bottom plus Reece 755A or approved equal
	12. please advise whether we will be provided a new control system, or tying into an existing system. If tying into existing, whose control system is currently in the facility	Will be tying into an existing control system that has yet to be installed by site.
	13. Will American Steel be a suitable alternate for Trussbuilt for the doors and frames? As I'm sure you are aware, they are both owned by the same company.	American steel and TrussBuilt are the same company. Both vendors are suitable to purchase products from
	14. For the 'Furnish Only' jobs, will the wire and conduit be supplied by the facility?	yes

PAGE #	QUESTION / COMMENT	STATE RESPONSE
	15. With the locks being keyed 2-sided, will there need to be an electric key switch on both sides of the door?	yes
	16. In addition to the key switch question above, please confirm if these will be "Inmate Key Switch Access Devices" or "Staff (Officer) Key Switch Access Devices". There are different model key switches called out depending on who has the access	Staff officer key
	17. Please confirm that the facility will be supplying the wiring for the (2) intercoms that are being installed in each new door	Facility will be supplying the wiring
	18. Please confirm if there needs to be an LED Indicator light on both sides of the door.	Yes indicator must be on both sides
	19. Please confirm that the facility requires 10 new keys per key code and 1 new key code created per pod, for a total of 160 Mogul keys.	1 code per pod is correct, total of 64 keys for 16 doors

3. **ITB Amendment Effective Date.** The revisions set forth herein shall be effective upon release. All other terms and conditions of this ITB not expressly amended herein shall remain in full force and effect.